# DA Gauge

## SWIVEL TYPE

**CAD FILE**

**DART**



Provide 5 mm or more clearance for A.

⚠ Do not use this gauge below the air pressure of 4kgf/cm².

### ■Table of Components

| No. | Description | Qty | Material and Remark |
|-----|-------------|-----|---------------------|
| ① | Gauge Base | 1 | FCD540 |
| ② | Stopper Plate | 1 | SS400 |
| ③ | Gauge Bracket | 1 | FCD540 |
| ④ | Joint | 1 | FCD540 |
| ⑤ | Arm | 1 | FCD540 |
| ⑥ | Cylinder Support | 2 | FCD540 |
| ⑦ | Rod | 1 | SS400 |
| ⑧ | Joint Pin (S) | 3 | S45C |
| ⑨ | Joint Pin 1 | 1 | S25C |
| ⑩ | Joint Pin 2 | 1 | S45C |

| No. | Description | Qty | Material and Remark |
|-----|-------------|-----|---------------------|
| ⑪ | Stopper Pin | 1 | SCM435 |
| ⑫ | Air Cylinder | 1 | CM2U32-35A(SMC) |
| ⑬ | Hexagon Socket Head Bolt | 4 | M8×25 |
| ⑭ | Washer | 7 | For M8 |
| ⑮ | Cotter Pin | 5 | φ2×16 |
| ⑯ | Cotter Pin | 1 | φ3×30 |
| ⑰ | Spring Washer | 4 | For M8 |
| ⑱ | Stopper | 2 | φ8×6 |
| ⑲ | Hexagonal Socket Set Screw | 1 | M6×8 |
| ⑳ | Hexagon Socket Head Bolt | 2 | M8×20 |

| Catalog No. | H |
|-------------|---|
|  | 75 |
|  | 100 |
|  | 125 |
| DART | 150 |
|  | 175 |
|  | 200 |
|  | 225 |
|  | 250 |

**Order**

| Catalog No. | H |
|-------------|---|
| DART | 150 |

⚠ DART is made to order.

Gauge